

# Cup Belt Upgrade

## Oxbo 8600 & 9000 Series Berry Harvester

The cup belt used on all the 8600 and 9000 series berry harvesters has been obsoleted by the manufacturer. Oxbo is offering new updated cup belts for the 8600 and 9000 berry harvesters



Parts Needed to Replace One Side of a Harvester		
Part Number	Description	Quantity
154225	Cup Belt	1
121856	Lower Cup Idler Assembly	1
59526	Sprocket	3
59527	Sprocket	3
101747	Set Collar Square	4
122999	Set Collar Square	4

**\*Please allow 30 days for delivery**

Contact your dealer or call 360-354-1500 ext. 3 for more information.