

Lower Belt Tensioner Upgrade



The improved roller design allows for better tracking on the belt and replaces the front sprockets for the lower belt. The kit number is **603552** and contains the rollers and set collars to swap a whole harvester.



1 - New Part

Models	Affected
Model	Year
7420	2007-2017
7440	2018-2022
7450	2021

Contact your dealer or call 360-354-1500 ext. 3 for more information.

