

Oxbo 6220

Trunk Shaking System

Oxbo presents the Trunk Shaker Skis and Isolators. This system is designed to be durable and outlast competition in the market. The complete assembly is also available for quick turnaround in the field (Part Number 153902).



ADVANTAGES

- ✓ Employs a “fail-safe” model, i.e. the skis will not fall off and cause damage if the isolator fails
- ✓ Wear strips are completely welded for a durable and smooth edge
- ✓ Skis available in two different lengths to adapt to field conditions




Skis and Lower Arms		
Part Number	Description	Quantity Per Harvester
152943	SKI WELDMENT (Standard)	2
152030	SKI WELDMENT (Long Option)	2
151792	LOWER ARM WELDMENT (Standard)	4
151268	LOWER ARM WELDMENT (Long Option)	4



ADVANTAGES FOR ISOLATORS

- ✓ Resilient and robust design
- ✓ Isolators can be easily charged, repaired and reused



A

Repair Isolator Parts

Part Number	Description	Quantity Per Harvester
152947	ISOLATOR MOUNT	4
153709	BUSHING	4
153733	BUSHING INSERT	4
KF5111	3/8NC X 4 HEX HEAD CAP SCREW	16
KF5458	3/8NC NYLOC NUT	16
KF5459	1/2NC NYLOCK	4
KF8002	1/2NC x 4-1/2 HEX HEAD CAP SCREW	4
153902	LOWER SKI BUSHING ASSEMBLY	4

Contact your nearest OXBO location for more information or call 800-628-6196 ext. 3